





Dairy Research and Teaching Facility

Construction Photos – March 5, 2012

 A long, narrow concrete foundation for a main barn structure, partially covered in snow, with trees in the background.	 A view looking down into a manure pit under construction, showing concrete walls and a metal grate.
<p>View of Main Barn</p>	<p>In barn manure pit</p>
 A large, flat concrete area for a feed area, with snow on the ground and some construction equipment in the distance.	 A construction site showing the back of a metabolic wing, with an excavator and orange safety fencing.
<p>Feed Area</p>	<p>Back of Metabolic Wing</p>